

## ASTM GUIDE TO CARE SYMBOLS

 <b>Wash</b>	<u>Machine wash cycles</u> <b>&amp;</b> <u>Water temperatures (maximum)</u> symbol (s) dots & °C.	 normal  permanent press  delicate / gentle	 hand wash	<b>Warning symbols for laundering</b>  do not wash  do not bleach  do not dry (used with do not wash)  do not iron		
 <b>Bleach</b>		 any bleach when needed	 only non-chlorine bleach when needed			
 <b>Dry</b>	<u>Tumble dry cycles</u> <b>&amp;</b> <u>Tumble dry heat setting</u>	 normal  permanent press  delicate / gentle	 line dry / hang to dry	<b>Additional instructions (in symbols or words)</b>  do not wring  do not tumble dry  dry flat		
 <b>Iron</b>	<u>Iron when needed--dry or steam</u> maximum temperature	 200°C (390°F) high	 150°C (300°F) medium			
 <b>Dryclean</b>	<u>Dryclean - normal cycle</u>	 any solvent	 perchlorethylene or petroleum solvent	 petroleum solvent only	<u>Dryclean - modified cycle</u>	 no steam (added to iron)