

CONVERSION CHART: FRACTION/DECIMAL/MILLIMETER

fraction	decimal	mm		fraction	decimal	mm		fraction	decimal	mm
1/64	0.0156	0.3969		1 1/64	1.0156	25.7969		2 1/64	2.0156	51.1969
1/32	0.0313	0.7938		1 1/32	1.0313	26.1938		2 1/32	2.0313	51.5938
3/64	0.0469	1.1906		1 3/64	1.0469	26.5906		2 3/64	2.0469	51.9906
1/16	0.0625	1.5875		1 1/16	1.0625	26.9875		2 1/16	2.0625	52.3875
5/64	0.0781	1.9844		1 5/64	1.0781	27.3844		2 5/64	2.0781	52.7844
3/32	0.0938	2.3813		1 3/32	1.0938	27.7813		2 3/32	2.0938	53.1813
7/64	0.1094	2.7781		1 7/64	1.1094	28.1781		2 7/64	2.1094	53.5781
1/8	0.125	3.175		1 1/8	1.125	28.575		2 1/8	2.125	53.975
9/64	0.1406	3.5719		1 9/64	1.1406	28.9719		2 9/64	2.1406	54.3719
5/32	0.1563	3.9688		1 5/32	1.1563	29.3688		2 5/32	2.1563	54.7688
11/64	0.1719	4.3656		1 11/64	1.1719	29.7656		2 11/64	2.1719	55.1656
3/16	0.1875	4.7625		1 3/16	1.1875	30.1625		2 3/16	2.1875	55.5625
13/64	0.2031	5.1594		1 13/64	1.2031	30.5594		2 13/64	2.2031	55.9594
7/32	0.2188	5.5563		1 7/32	1.2188	30.9563		2 7/32	2.2188	56.3563
15/64	0.2344	5.9531		1 15/64	1.2344	31.3531		2 15/64	2.2344	56.7531
1/4	0.25	6.35		1 1/4	1.25	31.75		2 1/4	2.25	57.15
17/64	0.2656	6.7469		1 17/64	1.2656	32.1469		2 17/64	2.2656	57.5469
9/32	0.2813	7.1438		1 9/32	1.2813	32.5438		2 9/32	2.2813	57.9438
19/64	0.2969	7.5406		1 19/64	1.2969	32.9406		2 19/64	2.2969	58.3406
5/16	0.3125	7.9375		1 5/16	1.3125	33.3375		2 5/16	2.3125	58.7375
21/64	0.3281	8.3344		1 21/64	1.3281	33.7344		2 21/64	2.3281	59.1344
11/32	0.3438	8.7313		1 11/32	1.3438	34.1313		2 11/32	2.3438	59.5313
23/64	0.3594	9.1281		1 23/64	1.3594	34.5281		2 23/64	2.3594	59.9281
3/8	0.375	9.525		1 3/8	1.375	34.925		2 3/8	2.375	60.325
25/64	0.3906	9.9219		1 25/64	1.3906	35.3219		2 25/64	2.3906	60.7219
13/32	0.4063	10.3188		1 13/32	1.4063	35.7188		2 13/32	2.4063	61.1188
27/64	0.4219	10.7156		1 27/64	1.4219	36.1156		2 27/64	2.4219	61.5156
7/16	0.4375	11.1125		1 7/16	1.4375	36.5125		2 7/16	2.4375	61.9125
29/64	0.4531	11.5094		1 29/64	1.4531	36.9094		2 29/64	2.4531	62.3094
15/32	0.4688	11.9063		1 15/32	1.4688	37.3063		2 15/32	2.4688	62.7063
31/64	0.4844	12.3031		1 31/64	1.4844	37.7031		2 31/64	2.4844	63.1031
1/2	0.5	12.7		1 1/2	1.5	38.1		2 1/2	2.5	63.5
33/64	0.5156	13.0969		1 33/64	1.5156	38.4969		2 33/64	2.5156	63.8969
17/32	0.5313	13.4938		1 17/32	1.5313	38.8938		2 17/32	2.5313	64.2938
35/64	0.5469	13.8906		1 35/64	1.5469	39.2906		2 35/64	2.5469	64.6906
9/16	0.5625	14.2875		1 9/16	1.5625	39.6875		2 9/16	2.5625	65.0875
37/64	0.5781	14.6844		1 37/64	1.5781	40.0844		2 37/64	2.5781	65.4844
19/32	0.5938	15.0813		1 19/32	1.5938	40.4813		2 19/32	2.5938	65.8813
39/64	0.6094	15.4781		1 39/64	1.6094	40.8781		2 39/64	2.6094	66.2781
5/8	0.625	15.875		1 5/8	1.625	41.275		2 5/8	2.625	66.675
41/64	0.6406	16.2719		1 41/64	1.6406	41.6719		2 41/64	2.6406	67.0719
21/32	0.6563	16.6688		1 21/32	1.6563	42.0688		2 21/32	2.6563	67.4688