

FRACTION-DECIMAL CONVERSION CHART

	<u>INCHES</u>	<u>MILLIMETERS</u>
	 $\frac{1}{64}$	.015625
	 $\frac{3}{64}$	.03125
	 $\frac{5}{64}$	.046875
	 $\frac{7}{64}$	.109375
	 $\frac{9}{64}$	.140625
	 $\frac{11}{64}$	.171875
	 $\frac{13}{64}$	.203125
	 $\frac{15}{64}$	.234375
	 $\frac{17}{64}$	.265625
	 $\frac{19}{64}$	.296875
	 $\frac{21}{64}$	.328125
	 $\frac{23}{64}$	.359375
	 $\frac{25}{64}$	.390625
	 $\frac{27}{64}$	.421875
	 $\frac{29}{64}$	.453125
	 $\frac{31}{64}$	.484375
		.500
		1.000

	<u>INCHES</u>	<u>MILLIMETERS</u>
	 $\frac{33}{64}$	.515625
	 $\frac{35}{64}$	.546875
	 $\frac{37}{64}$	.578125
	 $\frac{39}{64}$	.609375
	 $\frac{41}{64}$	.640625
	 $\frac{43}{64}$	.671875
	 $\frac{45}{64}$	.703125
	 $\frac{47}{64}$	.734375
	 $\frac{49}{64}$	.765625
	 $\frac{51}{64}$	.796875
	 $\frac{53}{64}$	.828125
	 $\frac{55}{64}$	.859375
	 $\frac{57}{64}$	.890625
	 $\frac{59}{64}$	.921875
	 $\frac{61}{64}$	.953125
	 $\frac{63}{64}$	.984375
		1.000