

Laundry Care



Machine Wash



Machine Wash



Machine Wash



Do Not Wash



80 F/30 C



105 F/40 C



120 F/50 C



Hand Wash



Do Not Wring



Professional Clean



Do Not Dry Clean



Any Solvent



Any Solvent Expect Tetrachlorethylene



Petroleum Solvent Only



Bleach If needed



Do Not Bleach



Chlorine Bleach If Needed



Non Chlorine Bleach



Dry



Do Not Dry



Tumble Dry



Do Not Tumble Dry



Dry Normal Low Heat



Dry Normal Med Heat



Dry Normal High Heat



Perm Press



Delicate



Hang to Dry



Drip Dry



Dry Flat



Dry In the Shade



Iron Any Temp/Steam



Do Not Iron



Max Temp 390 F/200 C



Max Temp 300 F/150 C



Max Temp 230 F/110 C



No Steam