

————— 0 — 0.000

$\frac{1}{64}$.015625

$\frac{1}{32}$.03125

$\frac{3}{64}$.046875

$\frac{1}{16}$.0625

$\frac{5}{64}$.078125

$\frac{3}{32}$.09375

$\frac{7}{64}$.109375

$\frac{1}{8}$.125

$\frac{9}{64}$.140625

$\frac{5}{32}$.15625

$\frac{11}{64}$.171875

$\frac{3}{16}$.1875

$\frac{13}{64}$.203125

$\frac{7}{32}$.21875

$\frac{15}{64}$.234375

$\frac{1}{4}$.250

$\frac{17}{64}$.265625

$\frac{9}{32}$.28125

$\frac{19}{64}$.296875

$\frac{5}{16}$.3125

$\frac{21}{64}$.328125

$\frac{11}{32}$.34375

$\frac{23}{64}$.359375

$\frac{3}{8}$.375

$\frac{25}{64}$.390625

$\frac{13}{32}$.40625

$\frac{27}{64}$.421875

$\frac{7}{16}$.4375

$\frac{29}{64}$.453125

$\frac{15}{32}$.46875

$\frac{31}{64}$.484375

$\frac{1}{2}$.500

$\frac{33}{64}$.515625

$\frac{17}{32}$.53125

$\frac{35}{64}$.546875

$\frac{9}{16}$.5625

$\frac{37}{64}$.578125

$\frac{19}{32}$.59375

$\frac{39}{64}$.609375

$\frac{5}{8}$.625

$\frac{41}{64}$.640625

$\frac{21}{32}$.65625

$\frac{43}{64}$.671875

$\frac{11}{16}$.6875

$\frac{45}{64}$.703125

$\frac{23}{32}$.71875

$\frac{47}{64}$.734375

$\frac{3}{4}$.750

$\frac{49}{64}$.765625

$\frac{25}{32}$.78125

$\frac{51}{64}$.796875

$\frac{13}{16}$.8125

$\frac{53}{64}$.828125

$\frac{27}{32}$.84375

$\frac{55}{64}$.859375

$\frac{7}{8}$.875

$\frac{57}{64}$.890625

$\frac{29}{32}$.90625

$\frac{59}{64}$.921875

$\frac{15}{16}$.9375

$\frac{61}{64}$.953125

$\frac{31}{32}$.96875

$\frac{63}{64}$.984375

————— 1 — 1.000